

Operating Temperature	°C	-35°C to + 70°C (Derate linearly to 50% from +50°C to +70°C)
Storage Temperature	°C	-40°C To + 85°C
Humidity (Non Condensing)	----	Operating: 10 ~ 90%RH, Non-Operating: 10 ~ 95%RH