



- ۱- Operating temperature: -5°C to 60°C
- ۲- Storage temperature: -20°C to 75°C
- ۳- Operating humidity: 10% ~ 90% relative humidity , non-condensing Limits to be at 90% RH at max 50°C