



- 1- Operating temperature:  $-5^{\circ}\text{C}$  to  $60^{\circ}\text{C}$
- 2- Storage temperature:  $-20^{\circ}\text{C}$  to  $75^{\circ}\text{C}$
- 3- Operating humidity: 10%~90% relative humidity, non-condensing Limits to be at 90% RH at max  $50^{\circ}\text{C}$