

# Fresnel diffraction by abrupt change of amplitude, phase, coherency and polarization

The Abdus Salam **International Centre for Theoretical Physics** 

ramare - Trieste, Ital

WINTER COLLEGE on OPTICS in IMAGING SCIENCE 31 January - 11 February 201

Navid Farahi, Ali Motazedi Fard, Seyed Roohollah Hosseini, and M. Taghi Tavassoly

Department of Physics, University of Tehran, Kargar Shomally, Tehran 14394-547, Iran

Abatract:

Conventional Fresnel diffraction occurs as the path of a light beam is partly obstructed by an opaque object. In fact, in this process the amplitude of the beam experiences an abrupt change at the object boundary. Recently it is shown that an abrupt change in the phase of a part of light beam also leads to Fresnel diffraction. In this presentation we show that an abrupt change in the polarization and in the coherency of a part of light beam leads to Fresnel diffraction. We show how these new kinds of diffractions can be exploited for measuring film thickness, refractive index and optical constants of materials and diffusion constant in liquid-liquid diffraction.





**University of Tehran Department of Physics** 

#### Introduction


After A. A. Mickelson introduced his Interferometer in 1881, a lot of attentions focused on application of interference in metrology because Mickelson made it possible to change phase desirably in interference.

Subject of diffraction includes Fresnel diffraction (FD), Fraunhofer diffraction and far-field diffraction. Fraunhofer diffraction has many applications in describing optical systems and in spectrometry, but applications of FD is limited. The limitation is imposed by the nonlinearity of phase in FD and the inability to change the optical path difference (OPD) at will.

Conventional Fresnel diffraction occurs as the path of a light beam partly obstructed by an opaque object. In fact, in this process the amplitude of the beam experiences an abrupt change at the object boundary. Recently it is shown that an abrupt change in the phase of a part of light beam also leads to Fresnel diffraction [1]. Tavassoly and et.al has shown in this kind of diffraction it is possible to change phase at will. This has provided many applications including in the measurement of refractive index, displacement, film thickness and temperature profile around small objects. Meanwhile it has been shown that Fresnel diffraction can occur as a result of abrupt change in amplitude, phase, polarization and coherency.

2-By abrupt change in amplitude by reflecting from the boundary of two different materials.[2]

FD also happens by abrupt change of amplitude but not between zero and 1. This kind of diffraction happens by reflection at the boundary of two materials. (Fig. 2.)






Fig. 2. Diffraction by reflection from the border of Cu and Al thin film.





Fig. 5. FD pattern obtained by reflection a beam from the boundary of smooth and rough surfaces.

# **5-By abrupt change in polarization**

Finally it can be shown that FD can occur when a wavefront of light experiences an abrupt change in polarization.







Fig. 9. Diffraction patterns of the expanded He–Ne laser light diffracted from a BK7 wedge of apex angle  $\alpha \frac{1}{4}$  0:198°, immersed in (a) air, (b) water, (c) acetone, and in ethanol-water solutions of (d) 30% and (e) 80%. The slanted fringes at the center are the traces of the central dark fringe, whose location and intensity vary periodically by the change of the wedge thickness. The arrows represent the directions of the x and y axes in Fig.-8.

-	Liquid	- Refractive Index N	
	Water Acetone Ethanol	$\begin{array}{c} 1.3317 \pm 2 \times 10^{-4} \\ 1.3578 \pm 2 \times 10^{-4} \\ 1.3608 \pm 2 \times 10^{-4} \end{array}$	

Table 2 Refractive Indices of Three Different Liquids

**3-** Temperature profile around a thin wire carrying electric current [5]




## **Methods of producing FD**

**1- By abrupt change in amplitude** by obstructing a part of wavefront

# **3-** By abrupt change in phase

Also FD occurs when phase of a part of wavefront of light suddenly changes. This happens by reflecting a wave front from a step or passing through a transparent plate immersed in liquid or gas.[1,2,3,4]




- Fig. 3. FD from one dimensional phase step of height  $\lambda/8$ .
- 4- By abrupt change in coherency of light

Fig. 6. Diffraction pattern obtained by passing polarized light beam from the boundary of two perpendicular polarization with regions directions.

#### **Some Applications**

**1- Measurement of film thickness by** FD from a phase step



#### Fig. 7. Experimental setup.

No.	Film Thickness in nm for $\lambda = 532 \text{ nm}$	Film Thickness in nm for $\lambda = 633$ nm	Standard Deviation in nm for $\lambda = 532  \text{nm}$	Standard deviation in nm for $\lambda = 633  \text{nm}$
1	466	465	6.5	5.9
<b>2</b>	444	446	6.5	5.5
3	239	242	4.8	4.1
4	80	82	3.9	6.1
<b>5</b>	57	55	2.1	2.4
6	39	40	1.5	2

#### Table 1

thicknesses obtained for six Experimental

Fig. 10. Diffraction patterns of the light diffracted from a copper wire of thickness 0.4 mm carrying different electric currents after its original diffracted field had been suppressed by the field diffracted from another similar wire installed in the other arm of a MZI. (a) *I=0.12 A. (b) I=0.25 A. (c)* I=0.41 A. (d) The profiles of the intensity distributions of the corresponding diffraction patterns. (e) Diagram of the set up.

### Conclusions

This report shows that FD can occur by abrupt change in amplitude, phase, coherency and polarization which can have significant applications. FD by changing coherency provides measurement of coherent and incoherent light that it results in finding roughness of surfaces. FD by changing phase can be applied in measuring the temperature, refraction index, thin films thickness. FD by changing in polarization provides new generation of ellipsometers.

The conventional FD is produced by putting an opaque obstacle in the way of light beam. You can see the from a semi-infinite barrier. FD (Fig. 1.)

MMMM

Fig. 1. conventional FD caused by an opaque obstacle.

It is also seen that FD occurs when a part of a wavefront of light suddenly suffers from a change in coherency. This happens by reflection a coherent beam from the boundary between smooth and rough surfaces.




Fig. 4. Beam of light reflected from the boundary of smooth and rough surfaces.

samples of different thicknesses using two different wavelengths.

2- Optical refractometry based on FD from phase wedge [4]




Fig. 8. When a transparent wedge of small apex angle is illuminated by a monochromatic parallel beam of light, diffracted from the two sides of the hatched interface, produces a periodic diffraction pattern. (see Fig. 9.)

#### References

- 1- M. Taghi Tavassoly, Mohammad Amiri, Ahmad Darudi, Rasoul Aalipour, Ahad saber, and Ali-Reza Moradi, "Optical diffractometry," J. Opt. Soc. Am. A 26(3), (2009).
- 2- M. Amiri, and M. Taghi Tavassoly, "Fresnel diffraction from 1D and 2D phase steps in reflection and transmission modes, Opt. Commu. 272, (2007).
- 3- M. Taghi Tavassoly, Iman Moaddel-Haghighi, and Khosrow Hassani, "Application of Fresnel diffraction from phase step to the measurement of film thickness," Appl. Opt. 48(29), (2009).
- 4- M. Taghi Tavassoly, and Ahad saber, "Optical diffractometry based on Fresnel diffraction from a phase wedge," Opt. Lett. 35(21), (2010).
- 5- Rasoul Aalipour, M. Taghi Tavassoly, and Ahmad Darudi, "Superimposing the waves diffracted from two similar hot and cold wires provides the temperature profile around the hot one," Appl. Opt. 49(19), (2010).